




### Retenkit 508x508x30 - 2,5L

Item: 8696004



Retenkit protective tiles provide stability and comfort for machines and operators thanks to the homogeneous, non-slip support surface. Cells with drainage channels for the progressive and uniform filling of the tiles. Safe thanks to its leakproof monobloc tiling for potential spillage of liquids. Assembly by simply clipping the tiles together.





#### Weight: 1.4 kg Volume: 2.5 L

# **Specifications**

External (LxWxH): 508 mm x 508 mm x 30 mm

Spill Control volume: 2.5 L

Maximum densitiy: 1.9 g/cm3

RFID option: Yes
Material: PP

Temperature range: -10 °C to 40 °C

Fire retardant:

Standard Colour Pallet:

Pallet size mm x 1000 mm
Pallet Height: mm

461 Green PMS 348C

**Packaging** 

Units/Pallet (pc):

#### **Related Products**



8961004 - Drum support 1245x570x644

### **Accessories**





## **Feature and Benefits**

| - We grant a 2 year warranty on all purchased products - 2 years warranty- 100% plastics - no metal parts involved, prone to corrosion, easy to recycle - Clips - easy |
|--|
| assembly tiles by clicking them together.  |
|  |

#### www.Schoellerallibert.com

The information on this datasheet has been compiled with the greatest possible care. Nevertheless, the information provided may contain inaccuracies. Before you rely on the information provided, it must be confirmed in another way. Schoeller Allibert is not liable for any damage that occurs directly or indirectly as a result of relying on incorrect information in this datasheet.

Datasheet Roto Moulding | 14-11-2022

- Retention Immediate retention of (hazardous) products.
- Scalable system able to increase according to your specific needs.

www.Schoellerallibert.com
The information on this datasheet has been compiled with the greatest possible care. Nevertheless, the information provided may contain inaccuracies.

Before you rely on the information provided, it must be confirmed in another way. Schoeller Allibert is not liable for any damage that occurs directly or indirectly as a result of relying on incorrect information in this datasheet. Datasheet Roto Moulding | 14-11-2022